

Xylem Water Solutions USA, Inc.

5771 Country Lakes Drive Fort Myers, Florida 33905 Phone: 239-693-5226 Fax: 239-693-1485

Date: March 21st, 2025

To: All Bidding Contractors

Quote# 2025-FTM-0161

Subject: PS 308.06 – Collier Co

We are pleased to offer the following equipment.

- (2) NP3171.185, 434 imp, 30hp/460v/3ph Flygt Pump w/50' Cable, Prepared for Flush Valve
- (1) Flush valve
- (1) Duplex Control Panel, 460V/30HP/3PH
- (2) 25'x1/4" Lift Chain
- (2) 6x6" Straight Through Discharge Connection
- (2) Adhesive Anchoring
- (2) Adhesive Nozzle
- (8) Threaded Rod
- (100) 2" Guide Rail
 - (2) 2" Upper Guide Bar Bracket
 - (1) Cable Holder
 - (2) 24x24x1/4" Base Plate
 - (1) AHD 42x82 Hatch (36x72" Clear Opening)
 - (1) Start Up Charge

Terms & Conditions

This order is subject to the Standard Terms and Conditions of Sale – Xylem Americas effective on the date the order is accepted which terms are available at <u>http://www.xyleminc.com/en-us/Pages/terms-</u> <u>conditions-of-</u> <u>sale.aspx</u> and incorporated herein by reference and made a part of the agreement between the parties.

Purchase Orders: Freight Terms:	Please make purchase orders out to:Xylem Water Solutions USA, Inc.3 DAP - Delivered At Place 08 - Jobsite(per IncoTerms 2020)See Freight Payment (Delivery Terms) below.
Taxes:	State, local and other applicable taxes are not included in this quotation.
Back Charges:	Buyer shall not make purchases nor shall Buyer incur any labor that would result in a back charge to Seller without prior written consent of an authorized employee of Seller.
Tariff Changes:	The prices quoted herein are based on the current tariff rates, duties, government charges, and trade regulations as of the date of this quote. If any new tariffs, duties, taxes, or similar charges are imposed, or any existing tariffs, duties, or charges are increased or modified by any government or regulatory authority (collectively, "Tariff Changes"), and such Tariff Changes result in an increase in the cost of goods, Xylem reserves the right to adjust the pricing of the affected goods to reflect the increased costs.
Shortages:	Xylem will not be responsible for apparent shipment shortages or damages incurred in shipment that are not reported within two weeks from delivery to the jobsite. Damages should be noted on the receiving slip and the truck driver advised of the damages.

